



PŘEVODOVÁ TABULKA ZRNITOSTÍ - TRIZACT

	ZRNITOSTI							
brusivo	Z 2500	Z 1200	Z 600	Z 400	Z 280	Z 240	Z 220	Z 120
trizact	A 6	A 16	A 30	A 45	A 65	A 80	A 100	A 160